

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number KSD007246846	2. Page 1 of 1	3. Emergency Response Phone 1800/465-3718	4. Manifest Tracking Number 008037576 FLE	
5. Generator's Name and Mailing Address Clean Harbors Kansas LLC 2549 North New York Street Wichita, KS 67219 (316) 269-7400			Generator's Site Address (if different than mailing address) SAME			
6. Transporter 1 Company Name U.S. Bulk Transportation Inc			U.S. EPA ID Number PA9787347515			
7. Transporter 2 Company Name			U.S. EPA ID Number			
8. Designated Facility Name and Site Address Clean Harbors Lone Mountain LLC 40385 S County Road 236 Wavoka, OK 73860 (580) 697-3500			U.S. EPA ID Number OKD065438376			
9a. HM			9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))		10. Containers	11. Total Quantity
				No.	Type	12. Unit Wt./Vol.
X	1. RA3077, HAZARDOUS WASTE, SOLID, N.O.S., POOL, POOL, B, PG III		1	DT	EST 16	Y
	2.					
	3.					
	4.					
13. Waste Codes						
1002 1002 1003						
F004 F005						
14. Special Handling Instructions and Additional Information 1. CH801502X06 CB#171 TRA 573 TLH 573A						
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.						
Generator's/Officer's Printed/Typed Name Jim Tyson			Signature Jim Tyson		Month 2	Day 5
					Year 15	
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:						
17. Transporter Acknowledgment of Receipt of Materials						
Transporter 1 Printed/Typed Name James H. Williams			Signature James H. Williams		Month 2	Day 5
Transporter 2 Printed/Typed Name			Signature		Year 15	
18. Discrepancy						
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
18b. Alternate Facility (or Generator) Manifest Reference Number: U.S. EPA ID Number						
Facility's Phone:						
18c. Signature of Alternate Facility (or Generator) Month Day Year						
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
1. H132		2.		3.		4.
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
Printed/Typed Name			Signature		Month	Day
					Year	

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number MSD0007246846	2. Page 1 of 1	3. Emergency Response Phone (800) 483-3718	4. Manifest Tracking Number 008037576 FLE		
5. Generator's Name and Mailing Address Clean Harbors Kansas LLC 2549 North New York Street Wichita, KS 67219 (316) 269-7400			Generator's Site Address (if different than mailing address) SAME				
6. Transporter 1 Company Name U.S. Bulk Transportation Inc			U.S. EPA ID Number PA0987347515				
7. Transporter 2 Company Name			U.S. EPA ID Number				
8. Designated Facility Name and Site Address Clean Harbors Lone Mountain LLC 40355 S County Road 236 Wannoka, OK 73860			U.S. EPA ID Number OKD065438376				
Facility's Phone: (580) 697-3500							
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
			No.	Type			
	X	1. HA3077, HAZARDOUS WASTE, SOLID, N.O.S., (F001, F003), 9. PG III	1	DT	EST 16	Y	F001 F002 F003 F004 F005
		2.					
		3.					
		4.					
14. Special Handling Instructions and Additional Information 1. CH931502X05 ERG2171 TRA# 573 TL# 573A							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offor's Printed/Typed Name Jim Tyson							
Signature <i>Jim Tyson</i>							
Month Day Year 12 5 15							
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:						
	17. Transporter Acknowledgment of Receipt of Materials						
	Transporter 1 Printed/Typed Name James H. Wines						
Signature <i>James H. Wines</i>							
Month Day Year 12 5 15							
Transporter 2 Printed/Typed Name							
Signature							
Month Day Year							
DESIGNATED FACILITY	18. Discrepancy						
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
	Manifest Reference Number:						
	18b. Alternate Facility (or Generator) U.S. EPA ID Number						
	Facility's Phone:						
18c. Signature of Alternate Facility (or Generator)							
Month Day Year							
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1. H132		2.		3.		4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a							
Printed/Typed Name David Ray							
Signature <i>David Ray</i>							
Month Day Year 12 5 15							